

## SOLIDWORKS Shortcuts

Ctrl + S	Save
Ctrl + Z	Undo
Enter	Repeat last command
Ctrl + P	Print
Ctrl + N	New Document
Ctrl + O	Open
Ctrl + W	Close
Ctrl + B	Rebuild
Ctrl + Q	Forced Rebuild
Ctrl + Shift + Z	Previous View
Ctrl + A	Select All
Ctrl + C	Copy
Ctrl + X	Cut
Ctrl + V	Paste
Ctrl + Shift + C	Copy Appearance
Ctrl + Shift + V	Paste Appearance

Arrow Keys	Rotate view 15°
Shift + Arrow Keys	Rotate view 90°
Alt + Left/right arrows	Roll view to normal screen
Ctrl + Arrow keys	Pan View
Shift + Z	Zoom in
Z	Zoom out
F	Zoom to Fit
G	Magnifying Glass
S	Shortcut Bar
R	Browse Recent Documents
I	Isometric View
T	Trimetric View
W	Search Commands
O	Search Community Forum
H	Search Help

Spacebar	View Orientation
Ctrl + spacebar	View Selector
Ctrl + 1	Front View
Ctrl + 2	Back View
Ctrl + 3	Left View
Ctrl + 4	Right View
Ctrl + 5	Top View
Ctrl + 6	Down View
Ctrl + 7	Isometric View
Ctrl + 8	Normal to

F5	Show/Hide Filter toolbar
F6	Filter off
F7	Spell Check
F8	Hide/Show Display Pane
F9	Hide/Show Feature Manager
F10	Hide/Show Command manager
Ctrl + F1	Hide/Show Task Pane
Shift + F3	Toggle Notes Upper Case
TAB	Hide the Hovered-over Component
Shift + TAB	Show the Hovered-over Component