

SOLIDWORKS Shortcuts

| | |
|------------------|---------------------|
| Ctrl + S | Save |
| Ctrl + Z | Undo |
| Enter | Repeat last command |
| Ctrl + P | Print |
| Ctrl + N | New Document |
| Ctrl + O | Open |
| Ctrl + W | Close |
| Ctrl + B | Rebuild |
| Ctrl + Q | Forced Rebuild |
| Ctrl + Shift + Z | Previous View |
| Ctrl + A | Select All |
| Ctrl + C | Copy |
| Ctrl + X | Cut |
| Ctrl + V | Paste |
| Ctrl + Shift + C | Copy Appearance |
| Ctrl + Shift + V | Paste Appearance |

| | |
|-------------------------|----------------------------|
| Arrow Keys | Rotate view 15° |
| Shift + Arrow Keys | Rotate view 90° |
| Alt + Left/right arrows | Roll view to normal screen |
| Ctrl + Arrow keys | Pan View |
| Shift + Z | Zoom in |
| Z | Zoom out |
| F | Zoom to Fit |
| G | Magnifying Glass |
| S | Shortcut Bar |
| R | Browse Recent Documents |
| I | Isometric View |
| T | Trimetric View |
| W | Search Commands |
| O | Search Community Forum |
| H | Search Help |

| | |
|-----------------|------------------|
| Spacebar | View Orientation |
| Ctrl + spacebar | View Selector |
| Ctrl + 1 | Front View |
| Ctrl + 2 | Back View |
| Ctrl + 3 | Left View |
| Ctrl + 4 | Right View |
| Ctrl + 5 | Top View |
| Ctrl + 6 | Down View |
| Ctrl + 7 | Isometric View |
| Ctrl + 8 | Normal to |

| | |
|-------------|---------------------------------|
| F5 | Show/Hide Filter toolbar |
| F6 | Filter off |
| F7 | Spell Check |
| F8 | Hide/Show Display Pane |
| F9 | Hide/Show Feature Manager |
| F10 | Hide/Show Command manager |
| Ctrl + F1 | Hide/Show Task Pane |
| Shift + F3 | Toggle Notes Upper Case |
| TAB | Hide the Hovered-over Component |
| Shift + TAB | Show the Hovered-over Component |